

TSPL2 V5.23 Firmware Modification History

TSPL2 Modifications

1. Modify the problem of nested IF ELSEIF ENDIF loop.
2. Use MONOTYPE TTF engine.
3. Add codepage 1250, 1252, 1253, 1254, 1255, 1256, 1257, 1258, ISO-8859-1, ISO8859-2, ISO-8859-3, ISO-8859-4, ISO-8859-5, ISO-8859-6, ISO-8859-7, ISO-8859-8, ISO-8859-8, ISO-8859-9, ISO-8859-10, ISO-8859-15.

These codepages are only supported when using TTF font.

4. Add centronic error status.
5. Modify the problem of BITMAP command.
6. Modify the checksum calculation of CODE 39C.