

## **TSPL V5.23 Firmware Modification History**

### **TSPL Modifications**

1. Modify the problem of nested IF ELSEIF ENDIF loop.
2. Add centronic error status.
3. Modify the problem of BITMAP command.
4. Modify the checksum calculation of CODE 39C.